

San Juan Country Club Cart Mechanic 2010 Billing*

Change single battery	\$15 flat rate plus parts
Change 6 batteries; straight switch out	\$80 flat rate plus parts
Change 6 batteries with battery rack cleaning/paint	\$180 flat rate plus parts (rack cleaning is to get any acid residue off, recommended on older carts or carts with leaky batteries, etc)
Replace and clean battery posts and wires	Per hour charges as labor** (like electrical)
Replace drive belt or alternator belt	\$10 flat rate
Adjust brakes	\$30 flat rate
Replace brakes	\$30 flat rate per side plus parts
Tire replacement (off old and on new)	\$20 per tire flat rate plus tire
Tire sealant	\$15 per tire flat rate
Gas cart Tune up	\$60 flat rate plus parts
(Includes oil change, oil filter(some have), fuel filter, new plugs, air filter, grease chassis)	
Motor computer/controller work	\$150 flat rate plus parts
Adjust and repairs of gas/brake petals	\$80 flat rate plus parts
Replace front or rear leaf spring	\$30 flat rate per side plus parts (Tony recommends replace both sides)
Charger Work	Per hour charges as labor plus parts, 1 hour minimum**
Electrical Work	Per hour charges as labor plus parts, 1 hour minimum**
Welding Work	Per hour charge plus parts, 1 hour minimum**

*This list is not meant to be all inclusive; every case is individual so if clarification is needed contact Proshop and they will contact Joe or Tony. Most basic services are included here.

**Tony's hourly billed rate for labor is \$30 per hour for 2010

Remember we have access to help from Robinson Golf Cars Service(Montrose) and others if work cannot be completed by Tony Jackson we can seek other assistance if warranted

